

CAL: 300 WIN MAG

PROJECT # 241314

BARBER - 5.22.06r0003633

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
SW/PA	12/19/03	Out of box Inspection	TLW 1303		
JS	12/22/03	De-Torque Scope	Cross-Bolt screws Front 25 Rear 25		
BL		Head space	Min t. .005		
BL		Proof	OK	1	1
BL	12/22/03	Head space	Min t. .005		
JS/BL	12/22/03	Depth Front Take down Screws hole			
BL	12/23/03	Firing Pin Indents	.021 - .0215 .022 Avg. .0213		
JS	12-29-03	Sear/Trigger Engagement	Arg. .0282		
JS	12-29-03	Sear lift	.0166		
SW/JS	1/13/04	Change out bolt head			
SW/JS	1/13/04	Head space	Min t. .006		
SW/JS	1/13/04	Proof Rd		1	2
SW/JS	1/13/04	Head space after proof	Min t. .007		
B Lee	1/15/04	200yd Jack Funct. Test	Magazine Bolt hard to close From Magazine well / 4 FTE Bolt hard to close	200	202
SW	1-15-04	Head space Min t. .007	(Front Take down screw loose)		
BL	1-16-04	Shoulder Fire	Bolt hard to close / 1 FTE	20	222
JS/BL	1-20-04	Clean & Inspect	See Inspection sheet		

Logform

Confidential - Submitter ID: 2706008639 Order

ET20012

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-22

TLW #: TLW1303

Date: 01 / 19 / 04Inspector: JS/BLRound Level: 222☒ Measure Headspace min⁺ .007☒ Sear Engagement: 1st. 0264 2nd. 0268 3rd. 0256Ave. 0262 spec. .020" to .025" 83☐ Trigger Pull: 1st. 4.920 2nd. 5.328 3rd. 5.244Ave. 5.164 spec. 4 lb. to 5.5 lb.☒ Check Take-Down Screws and Re-tighten if necessary.☒ Inspect extractor & bolt face area. Broken extractor☒ Inspect cam surface, locking lugs and bolt stop for signs of excessivewear: Locking lugs some wear; Bolt stop some wear☒ Inspect stock for any signs of cracking or other failure.☒ Other items ofnote: magazine Box protruding

TLW1303

Remington Confidential

ET20013