

CAL: 300 WIN MAG

M/710 MAGNUM TRIAL PILOT TEST

PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
SW/PA	12/19/03	Out of box Inspection	TLW1303A		
JS	12/22/03	Detorque Scope Cross Bolt Screws	front 35 Rear 30		
BL		Head space	min +.004		
BL		Proof	OK	1	1
BL	12/22/03	Head space	min +.004		
JS/BL	12/22/03	Depth Front Take down Screw hole			
BL	12/23/03	Firing Pin Indent	.022-.022-.020 Avg .0213		
JS	12-29-03	Seat/Trigger Engagement	Arg. .0261		
JS	12-29-03	Seat lift	.0159		
SW/JS	1/13/04	Change out bolt head			
SW/JS	1/13/04	Head space	Min +.005		
SW/JS	1/13/04	Proof RD		1	2
SW/JS	1/13/04	Head space after proof	Min +.005		
SW	1/15/04	200 Rd Basic Jack Function Test		200	202
SW	1-15-04	Head space Min +.005			
BL	1-16-04	Shoulder Fire	OK	20	222
JS/BL	1-20-04	Clean & Inspect	See Inspection Sheet		

Logform

ET20022

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-27

TLW #: TLW1303

Date: 01/20/04

Inspector: JS/BL

Round Level: 222

☒ Measure Headspace min. 0.05

☒ Sear Engagement: 1st. 0.025 2nd. 0.0255 3rd. 0.0247

Ave. 0.025 spec. 0.020" to 0.025" 83

☒ Trigger Pull: 1st. 4.269 2nd. 4.471 3rd. 4.298

Ave. 4.346 spec. 4 lb. to 5.5 lb.

☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area.

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: locking lugs somewhat

☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of

note: magazine Box protruding

TLW1303

Remington Confidential

ET20023