

GUN # A-4

SERIAL # 71146737

CAL: 300 WIN MAG

M/710 MAGNUM TRIAL PILOT TEST

TRACKING # TLW 1303

PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS RDS. FIRED	AT START-0 TOTAL RDS.
SW/PR	12/19/02	Out of box Inspection	TLW1303A		
JS	12/22/03	De-torque SCAR (ROSS Bolt)	Front joint lb Rear 30 in lb		
BL	12/22/03	Head space	Min +.002		
BL	12/22/03	Proof	Bolt flight opening	1	1
BL	12/22/03	Head space	Min +.002		
JS/BL	12/22/03	Depth front Take down	Scrub hole		
BL	12/23/03	Firing Pin Indents	would not take crusher holder for indents		
JS	12-29-03	Sear/Trigger Engagement	Arg. .0274		
JS	12-29-03	Sear lift	.0152		
SW/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Head space	Min +.005		
SW/JS	1/13/04	Proof Rod		1	2
SW/JS	1/13/04	Head space after proof	Min +.005		
BL	1/15/04	200rd Basic Jack Funct test	magazine box hard to take out / Bolt hard to close	200	202
SW/BL	1/15/04	Head space	Min .005		
BL	1-16-04	Shoulder function test	X20 Rds.	20	222
JS/BL	1-19-04	Inspect & Clean	See Inspection sheet		

Logform

BARBER - 5.22.06r0003735

Confidential - SW/PR 102206r0003735 Order
Williams v. Remington

ET20114

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-4

TLW #: TLW1303

Date: 01/19/04Inspector: JS/BLRound Level: 222☒ Measure Headspace min⁺.005☒ Sear Engagement: 1st. .02822 2nd. .0271 3rd. .0277Ave. .0274 spec. .020" to .025"☒ Trigger Pull: 1st. 4.576 2nd. 4.582 3rd. 4.247Ave. 4.468 spec- 4 lb. to 5.5 lb.☒ Check Take-Down Screws and Re-tighten if necessary.☒ Inspect extractor & bolt face area.☒ Inspect cam surface, locking lugs and bolt stop for signs of excessivewear: locking lugs some wear, excessive wear on bolt stop☒ Inspect stock for any signs of cracking or other failure.☒ Other items ofnote: insert has a defect must be in the mold.

TLW1303

Remington Confidential

ET20115