

CAL: 300 WIN MAG

TRACKING # TLW 1303
PROJECT # 241314

BARBER - 5.22.06r0003745

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS	AT START-0
				RDS. FIRED	TOTAL RDS
SW/PR	12/19/03	Out of box Inspection	TLW1303A		
JS	12/22/03	Detorque - Scope Crossbolt Screws	Front 15 Rear 27		
BL	12-22-03	Headspace	min +.004		
BL	12-22-03	Proof	OK	1	1
BL	12-22-03	Headspace	min +.004		
JS/BL	12-23-03	Depth Front Take down Screw hole			
BL	12-23-03	firing Pin Indent	.020 - .025 - .019 Avg. .0193		
JS	12-29-03	Gear/Trigger Engagement	Avg. .0341		
JS	12-29-03	Gear lift	.0162		
SW/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Headspace	Min +.005		
SW/JS	1/13/04	Proof Rd		1	2
SW/JS	1/13/04	Headspace after proof	Min +.005		
SW	1/14/04	200 Rd Basic Jack Function Test		200	202
SW/BL	1/15/04	Headspace	Min +.005		
DM	1-16-04	Shoulder function test X20 Rds.	Shot clean	20	222
JS/BL	1-19-04	Clean & Inspect	See Inspection sheet		

Logform

Confidential - ~~Subpoena~~ **Subpoena** ~~is.2106~~ **is.2106** ~~003745~~ **003745** Order
Williams v. Remington

ET20124

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-9

TLW #: TLW1303

Date: 01 / 19 / 04Inspector: JS/BLRound Level: 222
☒ Measure Headspace min + .005
☒ Sear Engagement: 1st. .0323 2nd. .0325 3rd. .0326
Ave. .0324 spec. .020" to .025" Rossy Eng
☒ Trigger Pull: 1st. 4.785 2nd. 5.001 3rd. 4.959
Ave. 4.915 spec- 4 lb. to 5.5 lb. .025
☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area.

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive
wear: Locking Lugs some wear, Bolt Stop some wear
☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of
note: magazine Box is protruding, receiver insert has a defect must be in the mold.

TLW1303

Remington Confidential

ET20125