

CAL: 300 WIN MAG

TRACKING # TLW 1303
PROJECT # 241314

BARBER - 5.22.06r0003767

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS	AT START-0
				RDS. FIRED	TOTAL RDS.
SW/BR	12/19/03	Out of box Inspection	THW1303A		
JS	12-22-03	Detorque - Scope Crosshairs	Front 25 Rear 25		
BL	12-22-03	Headspace	min + .005		
BL	12-22-03	Proof	OK	1	1
BL	12-22-03	Headspace	min + .005		
JS/BL	12-22-03	Depth Front Take down Screw hole			
BL	12-23-03	Fitting Pin Indentals	.014 10/23/03 19 Aug 2014		
JS	12-29-03	Gear/Trigger Engagement	Avg. .0281		
JS	12-29-03	Gear lift	.0112		
SW/JS	1/13/04	Change out Bolt Head			
SW/JS	1/13/04	Headspace Min + .007			
SW/JS	1/13/04	Proof Rd		1	2
SW/JS	1/13/04	Headspace after proof Min + .007			
JS	1-15-04	200 Rd. Jack Function test	Bolt difficult to close on. Rds. 81-100, 121-140	200	202
SW	1-15-04	Headspace Min + .007	(Front Take down screw missing , center was loose)		
BL	1-16-04	Shoulder Fire	Bolt hard to close	20	222
JS/BL	1-20-04	Clean & Inspect	See Inspection sheet		

Logform

Confidential - SUBORDER 52.001003767 Order

ET20146

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-20

TLW #: TLW1303

Date: 01 / 19 / 04Inspector: JS/BLRound Level: 222
☒ Measure Headspace min+.007.
☒ Sear Engagement: 1st. .0246 2nd. .025 3rd. .0248
Ave. .0248 spec- .020" to .025" 83
☒ Trigger Pull: 1st. 4.222 2nd. 4.777 3rd. 4.759
Ave. 4.586 spec- 4 lb. to 5.5 lb.
☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area.

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive

 wear: Bolt stop excessive wear, locking lugs some wear
☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of

 note: magazine Box protruding

TLW1303

Remington Confidential

ET20147