

CAL: 300 WIN MAG

TRACKING # TLW 1303
PROJECT # 241314

BARBER - 5.22.06r0003776

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS	AT START-0
				RDS. FIRED	TOTAL RDS.
SW/PA	12/19/03	Out of box Inspection	TLW1303A		
JS	12/22/03	Det torque Scope Cross Bolt Screws	Front 25 Rear 20		
BL		Headspace	Min +.002		
BL		Proof	OK	1	1
BL	12/22/03	Headspace	Min +.004		
JS/BL	12/22/03	Depth Front Take down screws			
BL	12/23/03	Firing Pin Indents	.031 - .030 - .019 Avg. .020		
JS	12-29-03	Seal/Trigger Engagement	Avg. .0288		
JS	12-29-03	Seal lift	.0168		
SW/JS	1/13/04	Change out bolt head			
SW/JS	1/13/04	Headspace	Min +.003		
SW/JS	1/13/04	Proof RD		1	2
SW/JS	1/13/04	Headspace after proof	Min +.004		
Blee	1/15/04	Load Jack Funct test	Bolt hard to close / magazine box hard to take from magazine well	200	202
SW	1-15-04	Headspace Min +.005	(Front Take down & Center screw loose)		
DL	1-16-04	Shoulder Fire	Bolt hard to close	20	222
JS/BL	1-20-04	Clean & Inspect	See Inspection Sheet		

Logform

10

Confidential - SUBINRTR 5.2.1067800376 Order

ET20155

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-25

TLW #: TLW1303

Date: 01 19 104Inspector: TS/BLRound Level: 222☒ Measure Headspace min + .004☒ Sear Engagement: 1st. 0273 2nd. 0258 3rd. 0268Ave. 0266 spec. .020" to .025" 83☒ Trigger Pull: 1st. 4.082 2nd. 4.193 3rd. 4.187Ave. 4.154 spec- 4 lb. to 5.5 lb.☒ Check Take-Down Screws and Re-tighten if necessary.☒ Inspect extractor & bolt face area.☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Bolt stop worn some☒ Inspect stock for any signs of cracking or other failure.☒ Other items ofnote: magazine Box protruding

TLW1303

Remington Confidential

ET20156