

CAL: 300 WIN MAG

TRACKING # TLW 1407
PROJECT # 241314

50
51

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
JW / BL	2/16/2004	OUT OF BOX	INSPECTION OK		
SW / BL	2/16/2004	HEADSPACE BEFORE	PROOF MIN + .002		
SW / BL	2/16/2004	PROOF ROUND		1	1
SW / BL	2/16/2004	HEADSPACE AFTER	PROOF MIN + .003		
SW / JW / BL	2/16/04	INDENTS			
SW / BL	2/17/04	SEAR LIFT	SEE DATA SHEET		
SW / BL	2/17/04	ENGAGEMENT	↓ ↓ ↓		
SW / BL	2/17/04	TRIGGER PULL			
BL	2/19/04	200 Rd JACK funct.		200	201
BL	2/24/04	500 Rd EXT. Endur test		500	701
BL	3/8/04	Clean/Inspection	See Inspection Sheet		

ET21092

Confidential - ~~Slaker~~ Order
-502P.060004092
Williams v. Remington

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-13

TLW #: TLW1303

Date: 03 / 8 / 04Inspector: BLRound Level: 701

- ☒ Measure Headspace min. .003
- ☒ Inspect Take Down Screws for loosening. Top screw 1/4 in turn 83
- ☒ Sear Engagement: 1st. .0336 2nd. .0341 3rd. .0343 Ave. .034 spec- .025" to .030"
- ☒ Reset Sear Engagement if Required: 1st. .0297 2nd. .0292 3rd. .0294 Ave. .02943
- ☒ Trigger Pull: 1st. 4.610 2nd. 4.785 3rd. 4.789 Ave. 4.728 spec- 4.5 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1st. 2nd. 3rd. Ave.
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: cam surface, locking lugs some sign of wear
- ☒ Inspect stock for any signs of cracking or other failure: cracked stock at center screw hole
- ☐ Other items of note:

TLW1216

Remington Confidential

ET21093