

CAL: 300 WIN MAG

TRACKING # TLW 1407
PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS	AT START-0
				RDS. FIRED	TOTAL RDS.
JW / BL	2/16/2004	OUT OF BOX	INSPECTION OK		
SW / BL	2/16/2004	HEADSPACE BEFORE	PROOF MIN + .005		
SW / BL	2/16/2004	PROOF ROUND		1	1
SW / BL	2/16/2004	HEADSPACE AFTER	PROOF MIN + .005		
SW / JW / BL	2/16/04	INDENTS			
SW / BL	2/17/04	SEAR LIFT	SEE DATA SHEET		
SW / BL	2/17/04	ENGAGEMENT	↓ ↓ ↓		
SW / BL	2/17/04	TRIGGER PULL			
JK	2/19/04	200 Rd JACK funct.		200	201
BL / JW	3/1/04	500 Rd Ext. Endur Test		500	201
CL	3/9/04	Clean/Inspection	See Inspection Sheet		

Logform

— **De**
— **De**

BARBER - 5.22.06r0004118

ET2118

Confidential - Sheriff's Office Order
 Sheriff - 502P0606641111
 Williams v. Remington

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-26

TLW #: TLW1303

Date: 3 / 9 / 04Inspector: BLRound Level: 701

- ☒ Measure Headspace mint .005
- ☒ Inspect Take Down Screws for loosening. Top screw 3/4 turn - Center 1/8 turn
- ☒ Sear Engagement: 1st. .0349 2nd. .0349 3rd. .0349 Ave. .0349 spec. .025" to .030"
- ☒ Reset Sear Engagement if Required: 1st. .0287 2nd. .0285 3rd. .0281 Ave. .02843
- ☒ Trigger Pull: 1st. 5.641 2nd. 5.719 3rd. 5.818 Ave. 5.659 spec- 4.5 lb. to 5.5 lb.
- ☒ Reset Trigger Pull if Required: 1st. 5.374 2nd. 5.244 3rd. 5.288 Ave. 5.275
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: cam surface, locking lugs, bolt stop some sign of wear
- ☒ Inspect stock for any signs of cracking or other failure. cracked stock at center screw hole
- ☐ Other items of note: _____

TLW1216

Remington Confidential

ET21119