

CAL: 300 WIN MAG

M/710 MAGNUM TRIAL AND PILOT TEST 1.1

TRACKING # TLW 1407
PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
JW / BL	2/16/2004	OUT OF BOX	INSPECTION OK		
SW / BL	2/16/2004	HEADSPACE BEFORE	PROOF MIN + .004		
SW / BL	2/16/2004	PROOF ROUND		1	1
SW / BL	2/16/2004	HEADSPACE AFTER	PROOF MIN + .005		
SW/JW/BL	2/16/04	INDENTS			
SW/BL	2/17/04	SEAR LIFT	SEE DATA SHEET		
SW/BL	2/17/04	ENGAGEMENT			
SW/BL	2/17/04	TRIGGER PULL			
JK	2/19/04	200 Rd Jack Funct.		200	201
BL/JW	3/1/04	500 Rd Ext. Endur Test		500	201
BL	3/9/04	Clean/Inspection	See Inspection sheet		

Logform

—**عز**
—**عز**

BARBER - 5.22.06r0004120

Confidential - ~~SHARPER~~ - 502F0610064120 Order
Williams v. Remington

ET21120

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-27

TLW #: TLW1303

Date: 3 19 104Inspector: BLRound Level: 701

- ☒ Measure Headspace min + .005
- ☒ Inspect Take Down Screws for loosening. Top screw 8 turn
- ☒ Sear Engagement: 1st. .0278 2nd. .0286 3rd. .0285 Ave. .0283 spec- .025" to .030"
- ☒ Reset Sear Engagement if Required: 1st. 2nd. 3rd. Ave.
- ☒ Trigger Pull: 1st. 5.001 2nd. 5.047 3rd. 5.087 Ave. 5.045 spec- 4.5 lb. to 5.5 lb.
- ☒ Reset Trigger Pull if Required: 1st. 2nd. 3rd. Ave.
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: cam surface, locking lugs, some sign of wear
bolt stop excessive wear
- ☒ Inspect stock for any signs of cracking or other failure: cracked stock at center screw hole
- ☐ Other items of note:

TLW1216

Remington Confidential

ET21121