

CAL: 300 WIN MAG

PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
SW/PA	12/19/03	Out of box Inspection	TWL1803A		
JS	12/22/03	Detonate Scope Cross Bolt screws	Front 25 in L6 Rear 27 in L6		
DL	12/22/03	Headspace	min +.001		
BL	12/22/03	Proof	Tight Opening	1	1
BL	12/22/03	Headspace	min +.004		
JIAL	12/22/03	Depth front take down screw hole			
BL	12/22/03	Firing Pin Indents	.020-.020-.019 A.g..0196		
JS	12-29-03	Gear/Trigger Engagement	Avg..0312		
JS	12-29-03	See 1st	.0149		
SW/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Headspace Min +.006			
SW/JS	1/13/04	Proof Rcl		1	2
SW/JS	1/13/04	Headspace after proof	Min +.007		
SW	1/14/04	200 Rd Basic Jack Function Test		200	202
SW/DL	1/18/04	Headspace	Min +.006		
JR	1-16-04	Shoulder function test X 20 Rds. Bolt difficult to close; Bolt hangs up on the shell feeding.		20	222
JS/BL	1-19-04	Clean & Inspect	See Inspection sheet Broken extractor		

Logform

ET21263

Williams v. Remington