

TRACKING # TLW 1303
PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS	AT START-0
				RDS. FIRED	TOTAL RDS.
SW/PA	12/19/03	Out of box Inspection	TLW1302A		
JS	12-22-03	Detonate - Scope Crosshair Screws	Front Rear		
BL	12-22-03	Headspace	min t. .004		
BL	12-22-03	Pract	OK	1	1
BL	12-22-03	Headspace	min t. .004		
JS/BL	12-23-03	Depth Front Take down	Screw hole		
BL	12-23-03	Firing Pin Indent	.021, .020, .021 Avg. .0206		
JS	12-29-03	Sear/Trigger Engagement	Avg. .0258		
JS	12-29-03	Sear lift	.0186		
SW/JS	1-13-04	Charge out Bolt Head			
SW/JS	1-13-04	Headspace	Min t. .006		
SW/JS	1-13-04	Pract Rd		1	2
SW/JS	1-13-04	Headspace after pract	Min t. .006		
JS	1-14-04	200 Rd. Basic "no function test"	Bolt head to case on #54/81-200; Magazine was bent at "top" side	200	202
SW/JS	1-15-04	Headspace	Min t. .007		
TC	1-16-04	Shoulder function test	X20 Rds. Shot clean	20	222
JS/BL	1-19-04	Clean & Inspect	See Inspection Sheet for Broken extractor		

Logform

BARBER - 5.22.06r0004283

Confidential - Submitter - 502-660-4285 Order

ET21283