

CAL: 300 WIN MAG

TRACKING # TLW 1303
PROJECT # 241314

				ROUNDS AT START-0	
NAME	DATE	TEST ACTIVITY	COMMENTS	RDS. FIRED	TOTAL RDS.
SW/PA	12-14-03	Out of box Inspection	TLW1303A		
JS	12-22-03	Detorque - Scope	Crossbolt Screws - Front 20 Rear 15		
BL	12-22-03	Headspace	min +.006		
BL	12-22-03	Proof	OK	1	1
BL	12-22-03	Headspace	min +.006		
JS/BL	12-22-03	Depth Front Take down	Screw holes		
BL	12-23-03	Firing Pin Indent	.020 - .020 - .021 Avg .0203		
JS	12-29-03	Coll/Trieger Engagement	Arg. .0274		
JS	12-29-03	Seq. lift	.0155		
SW/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Headspace	Min +.007		
SW/JS	1/13/04	Proof & Rd		1	2
SW/JS	1/13/04	Headspace after proof	Min +.007		
JS	1-15-04	200 Rd Jack Function Test	Bolt head to close on Rds 61-80; 121-140	200	202
SW	1-15-04	Headspace	Min +.007 (Front & Rear Take down screws were loose)		
BL	1-16-04	Shoulder Fire	Bolt hard to close	20	227
JS/BL	1-20-04	Inspect & Clean	See Inspection sheet - Broken extractor		

Logform

Confidential - Subject - 5.2.2.061004508 Order

ET21308

BARBER - 5:22.06r0004308