

CAL: 300 WIN MAG

TRACKING # TLW 1303
PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS	AT START-0
				RDS. FIRED	TOTAL RDS.
SW/PR	12/19/03	Out of box Inspection	TLW1303A		
JS	12/22/03	De-Torque Scope Base Bolt screws	Front 35 Rear 25		
BL		Headspace min 7.003		1	1
BL		PRIM F hard to open			
BL	12/22/03	Headspace min 7.004			
JS/BL	12/22/03	Depth Front Take down Screw hole	1.534		
JK	12/28/03	Extended Profile Test - Extractor pull out @ 76 Rds		76	77
		<u>Stopped Test</u>			

Logform

BARBER - 5.22.06r0004474

— 4 —

ET21474

Confidential - Subpoena Order
 Subpoena - 5:22 PM 6/6/04
 Williams v. Remington

PROJECT#	TLW#	SHOOTER
GUN	AMMO	DATE
	MALFUNCTION	MALFUNCTION
1	+ .004	51
2	+ .005	52
3	.005 Hard to Rotate, ejector jammed w/ Brass	53
4	.005	54
5	.005	55
6	.005	56
7	.005 Ejector jammed w/ Brass	57
8	.005	58
9	.006	59
	.006	.007
11		61
12		62
13		63
14		64
15	.006	65
16		66
17		67
18		68
19		69
	.006	.007
21		71
22		72
23		73
24	Safety Loose	74
26	.006	75
26		76 Extractor Housing Broke-
27		77
28		78
29		79
	.007	
31		81
32		82
33		83
34		84
35		85
36		86
37		87
38		88
39		89
	.007	
41		91
42		92
43		93
44		94
45		95
46		96
47		97
48		98
49		99
	.007	

ET21475