

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Extruded Receiver "Magnum Caliber"

Project: 241314

TLW #: TLW1689

Date: 3 / 1 / 05Gun Test # A-21S/N 71202763Round Level: 1731Inspector: B. LEE

- ☒ Measure Headspace min⁺ .005.
- ☒ Check Takedown Screw Torque @ Disassembly: Frt 45, Center 30, Rear 10.
- ☒ Sear Engagement: 1st .0259 2nd .0260 3rd .0257 Ave. .0258 spec- .025" to .030"
- ☐ Reset Sear Engagement if Required: 1st _____ 2nd _____ 3rd _____ Ave. _____
- ☒ Trigger Pull: 1st 5.694 2nd 5.715 3rd 5.741 Ave. 5.717 spec- 4.5 lb. to 6 lb.
- ☐ Reset Trigger Pull if Required: 1st _____ 2nd _____ 3rd _____ Ave. _____
- ☒ Inspect Firecontrol Insert for any signs of cracking or other failure. OK
- ☐ Other items of note: _____
- ☒ Torque Takedown Screws @ Reassembly: SPEC- Frt- 75 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.

TLW1216

Remington Confidential

ET21895