

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Extruded Receiver "Magnum Caliber"

Project: 241314

TLW #: TLW1689

Date: 2 / 24 / 05Gun Test # A-21S/N 71202765Round Level: 1231Inspector: B. LEE

- ☒ Measure Headspace min+.005
- ☒ Check Takedown Screw Torque @ Disassembly: Frt 40, Center 30, Rear 15
- ☒ Sear Engagement: 1st. .0241 2nd. .0255 3rd. .0248 Ave. _____ spec-.025" to .030"
- ☐ Reset Sear Engagement if Required: 1st. _____ 2nd. _____ 3rd. _____ Ave. _____
- ☒ Trigger Pull: 1st. 5.713 2nd. 5.639 3rd. 5.685 Ave. 5.679 spec- 4.5 lb. to 6 lb.
- ☐ Reset Trigger Pull if Required: 1st. _____ 2nd. _____ 3rd. _____ Ave. _____
- ☒ Inspect Firecontrol Insert for any signs of cracking or other failure. OK
- ☐ Other items of note: _____
- ☒ Torque Takedown Screws @ Reassembly: SPEC- Frt- 75 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.

TLW1216

Remington Confidential

ET21901