

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Extruded Receiver "Magnum Caliber"

Project: 241314

TLW #: TLW1689

Date: 2 122 105

Gun Test # A21

S/N 71202765

Round Level: 721

Inspector: B. LEE

- ☒ Measure Headspace min+.005
- ☒ Check Takedown Screw Torque @ Disassembly: Frt 45, Center 20, Rear 10
- ☒ Sear Engagement: 1st .0248 2nd .0245 3rd .0245 Ave. .0246 spec- .025" to .030"
- ☐ Reset Sear Engagement if Required: 1st _____ 2nd _____ 3rd _____ Ave. _____
- ☒ Trigger Pull: 1st 4.985 2nd 4.925 3rd 5.004 Ave. 4.971 spec- 4.5 lb. to 6 lb.
- ☐ Reset Trigger Pull if Required: 1st _____ 2nd _____ 3rd _____ Ave. _____
- ☐ Inspect Firecontrol Insert for any signs of cracking or other failure. OK
- ☐ Other items of note: _____
- ☒ Torque Takedown Screws @ Reassembly: SPEC- Frt- 75 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.

TLW1216

Remington Confidential