

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Extruded Receiver "Magnum Caliber"

Project: 241314

TLW #: TLW1689

Date: 2/22/05

Gun Test # A-35

S/N 71203034

Round Level: 719

Inspector: B. LEE

83

- Measure Headspace min+.005
- Check Takedown Screw Torque @ Disassembly: Frt 15, Center 25, Rear 15
- Sear Engagement: 1st .0288 2nd .0292 3rd .0296 Ave. _____ spec- .025" to .030"
- Reset Sear Engagement if Required: 1st _____ 2nd _____ 3rd _____ Ave. _____
- Trigger Pull: 1st 5.705 2nd 5.856 3rd 5.761 Ave. 5.774 spec- 4.5 lb. to 6 lb.
- Reset Trigger Pull if Required: 1st _____ 2nd _____ 3rd _____ Ave. _____
- Inspect Firecontrol Insert for any signs of cracking or other failure. OK
- Other items of note: _____

- Torque Takedown Screws @ Reassembly: SPEC- Frt- 75 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.

TLW1216

Remington Confidential

ET21953