-

Remington Arms Company Inc. Research & Development toxing conteres 315 West Ring Road Exabellionn, RY 42701 Clean & Inspect Checklist Model: 710 Extruded Receiver "Magnum Caliber" Inspect The State S		Confide	NTIAL	
Hodel: 710 Extruded Receiver "Magnum Caliber" Project: 241314 TLW#: TLW1689 Date:		Research & Developm 315 West F	ent Technical Center Ring Road	
Project: 241314 TLW#: TLW1689 Date: 2_122_135 Gun Test # A-32 Round Level: 7/9 Image: Imag		Clean & Ins	pect Checklist	
Date: 2. [22.] 0.5 Gun Test # <u>A-32</u> SN_ 7/2.02753 Round Level: <u>719</u> Inspector: <u>6.166</u> Measure Headspace <u>min. 6.09</u>		Model: 710 Extruded R	leceiver "Magnum Caliber"	
Gun Test #		Project: 241314	TLW#: TLW1689	
Round Level: _7!9 Inspector: _0.LEE		Date: 2 / 22 / 05		
Measure Headspace min.1.604 Check Takedown Screw Torque @ Disassembly: Frt_5Center_45Rear_45 Sear Engagement: 1 ^a		Gun Test # <u>4-32</u>	S/N 71202753	
Check Takedown Screw Torque @ Disassembly: Frt			Inspector: <u>B.LEE</u>	83
Sear Engagement: 1 st . <u>.0293</u> 2 nd . <u>.0303</u> 3 rd . <u>0249</u> Ave. <u>.0398</u> spec025" to.030" Reset Sear Engagement if Required: 1 st . 2 nd . 3 rd . Ave	2	Measure Headspace		1. 1
Reset Sear Engagement if Required: 1 st . 2 nd . 3 rd . Ave. Trigger Pull: 1 st . 5.346, 3 rd . Ave. 5.3 9.3 spec- 4.5 lb. to 6 lb. Reset Trigger Hull: 1 st . 2 nd . 3 rd . Ave.			<u>,Ceinterلک</u> ,Rear <u>_/ک</u>	
Trigger Pull: 1 st . <u>5</u> . <u>4</u> /0; 2 ^m . <u>5</u> . <u>3</u> , <u>5</u> . <u>4</u> , <u>3</u> , <u>5</u> . <u>4</u> , <u>6</u> , <u>5</u> . <u>4</u> , <u>7</u> . Ave. <u>5</u> . <u>3</u> , <u>8</u> , <u>5</u> . <u>8</u> , <u>8</u> , <u>8</u> , <u>8</u> , <u>8</u> , <u>8</u> , <u>5</u> . <u>4</u> , <u>6</u> , <u>7</u> , <u>7</u> . Reset Trigger Pull: 1 st . <u>2</u> , <u>a</u> , <u>3</u> , <u>3</u> , <u>7</u> . Ave	9	Sear Engagement: 1 st . <u>20293</u> 2 nd . <u>10303</u> 3 rd . 022	Ave. :0298 spec025" to.030"	
Reset Trigger Puill if Required 1 st 2 nd 3 rd Ave Inspect Firecontrol Insect for any signs of cracking or other failure				
Inspect Firecontrol Insect for any signs of cracking or other failure				
failure				
note: Torque Takedown Screws @ Reassembly: SPEC- Frt- 75 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.			her	 _
note: Torque Takedown Screws @ Reassembly: SPEC- Frt- 75 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.			<u></u> -	
Torque Takedown Screws @ Reassembly: SPEC- Frt- 75 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.				
			· · · · · · · · · · · · · · · · · · ·	
		······································		—
	đ	Torque Takedown Screws @ Reassembly: SPEC- Frt- 75	in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.	
TLW1216	_		. ,	
			т	LW1216
Remington Confidential		Remington Co	nfidential	

ET21994

-51-44