

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Extruded Receiver "Std. Caliber"

Project: 241314

TLW #: TLW1689

Date: 2 / 25 / 05

Gun Test # A-11

S/N 71202772

Round Level: 1211

Inspector: B LEE

- ☒ Measure Headspace min^t. 004.
- ☒ Check Takedown Screw Torque @ Disassembly: Frt 35, Center 30, Rear 15.
- ☒ Sear Engagement: 1st. .0248 2nd. .0246 3rd. .0244 Ave. .0246 spec-.020" to .025"
- ☐ Reset Sear Engagement if Required: 1st. _____ 2nd. _____ 3rd. _____ Ave. _____
- ☒ Trigger Pull: 1st. 5.341 2nd. 5.423 3rd. 5.422 Ave. 5.395 spec- 4 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1st. _____ 2nd. _____ 3rd. _____ Ave. _____
- ☒ Inspect Firecontrol Insert for any signs of cracking or other failure. OK
- ☒ Other items of note: * Bolt has a burr on one lug
* Inner receiver has a line where Bolt lug was scraping side wall.
- ☒ Torque Takedown Screws @ Reassembly: SPEC- Frt- 50 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.

TLW1216

Remington Confidential

ET22053