

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Extruded Receiver "Std. Caliber"

Project: 241314

TLW #: TLW1689

Date: 2 / 25 / 85

Gun Test # A-12

S/N 71202769

Round Level: 1211

Inspector: B. LEE

83

- ☒ Measure Headspace min. .002
- ☒ Check Takedown Screw Torque @ Disassembly: Frt 30, Center 30, Rear 15
- ☒ Sear Engagement: 1st. .0248 2nd. .0242 3rd. .0246 Ave. .0245 spec- .020" to .025"
- ☐ Reset Sear Engagement if Required: 1st. 2nd. 3rd. Ave.
- ☒ Trigger Pull: 1st. 4.961 2nd. 4.849 3rd. 4.980 Ave. 4.929 spec- 4 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1st. 2nd. 3rd. Ave.
- ☒ Inspect Firecontrol Insert for any signs of cracking or other failure. OK
- ☐ Other items of note:
- ☒ Torque Takedown Screws @ Reassembly: SPEC- Frt- 50 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.

TLW1216

Remington Confidential