

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Extruded Receiver "Std. Caliber"

Project: 241314

TLW #: TLW1689

Date: 2 / 17 / 05

Gun Test # A3

S/N 71203229

Round Level: 701

Inspector: B. LEE

83

- ☒ Measure Headspace min+.002.
- ☒ Check Takedown Screw Torque @ Disassembly: Frt 35, Center 25, Rear 10.
- ☒ Sear Engagement: 1st. .0245 2nd. .0247 3rd. .0247 Ave. .0244 spec-.020" to .025"
- ☐ Reset Sear Engagement if Required: 1st. _____ 2nd. _____ 3rd. _____ Ave. _____
- ☒ Trigger Pull: 1st. 6.147 2nd. 5.678 3rd. 5.970 Ave. 5.931 spec- 4 lb. to 5.5 lb.
- ☒ Reset Trigger Pull if Required: 1st. 5.036 2nd. 4.958 3rd. 5.105 Ave. 5.033
- ☒ Inspect Firecontrol Insert for any signs of cracking or other failure. OK
- ☐ Other items of note: _____
- ☒ Torque Takedown Screws @ Reassembly: SPEC- Frt- 50 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.

TLW1216

Remington Confidential