

GUN # A-9
SERIAL # 71126325
CAL 300 WIN MAG

DAT # 1 M/ 710 MAGNUM PRODUCTION RECEIVER INSERT

TRACKING # TLW1216
PROJECT #241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
SW/BL	7/21/03	Head space	Min +.006	TLW1216A	
SW/BL	7/21/03	Head space	Shoulder Gauge .221 will not close up	TLW1216A	
SW/BL	7/21/03	Firing Pin Indent	.020 - .018 Avg. .019	TLW1216D	
SW/BL	7/22/03	Trigger Pull	4.149, 3.975, 4.053 Avg. 4.059	TLW1216F	
SW/BL	7/22/03	Sear/Trigger Engagement	.0278, .0278, .0278 Avg. .0278	TLW1216E	
SW/BL	7/22/03	Sear Lift	.0224	TLW1216E	
SW/BL	7/22/03	Roset Sear/Trigger Engagement	.0232, .0230, .0231 Avg. .0231	TLW1216E	
SW/BL	7/22/03	Trigger Pull	4.721, 4.583, 4.645 Avg. 4.649	TLW1216F	
SW/BL	7/22/03	Firing Pin Head/Sear Engagement	.060	TLW1216F	
SW/BL	7/23/03	Safety ON Forces	5.475, 5.495, 5.685 Avg. 5.552	TLW1216G	
SW/BL	7/23/03	Safety OFF Forces	1.925, 1.860, 2.145 Avg. 1.977	TLW1216G	
SW/BL	7/24/03	Bolt Lift	16.78, 16.50, 16.42 Avg. 16.56	TLW1216H	
SW/BL	7/24/03	Bolt Close	6.50, 6.54, 6.48 Avg. 6.40	TLW1216H	
SW/BL	7/24/03	Bolt Lift w/ Dummy	16.48, 16.54, 15.88 Avg. 16.30	TLW1216H	
SW/BL	7/24/03	Bolt Close w/ Dummy	6.74, 6.38, 5.86 Avg. 6.32	TLW1216H	
SW/BL	7/25/03	Magazine Spring Force	Gauge 0.200 1.685 - 1.690 - 1.695 Avg. 1.690	TLW1216I	
SW/BL	7/29/03	Magazine Capacity Test	Pass - weak ejection	TLW1216D	
SW/BL	7/29/03	Check ISS system	Pass	TLW1216AT	
SW/BL	7/29/03	Twist Rate	1 Turn 10", 25	TLW1216N	
SW/BL	7/30/03	Bore diameter	Space .300/.301 Diameter .301, .300	TLW1216L	
SW/BL	8/1/03	Proof Test	Hammer bolt Back	TLW1216B	1
SW/BL	8/6/03	Head space After Proof	Min +.007	TLW1216C	
SW	8/7/03	Basic Jack Function Test	0 Malfunctions	TLW1216P	200
Gary H	8/12/03	Basic Shoulder Function Test	2 Malfunctions	TLW1216Q	20
			2 Bolt Stop Failed (bolt came out)		221
SW/BL	8-20-03	Cleaned		TLW1216S	
SW/BL	8-20-03	Inspection	Head space min +.007	TLW1216S	
SW/BL	8/25/03	Accuracy Test	20 Rds No Malfunctions	TLW1216T	20
SW/BL	9/5/03	Extended Function	Endurance Test - Total malfunctions 3 FTE		241
			Magazine Box hard to extract from magazine		
			well - Photo Taken	TLW1216R	500
BL	9/8/03	Cleaned		TLW1216S	741
SW/BL	9/8/03	Inspected	Head space Min +.007	TLW1216S	
SW/BL	9/11/03	SAAMI JAR-OFF Test	PASS	TLW1216X	

Logform