PROJECT # 241314 ENG: MIKE KEENEY SHOOTER:STEVE WADE

31.

HEAT AND HUMIDITY TEST GUN # A-8 SERIAL # 71126315 TRACKING # TLW1116AL DATE

- # 1 PLACE GUN A -8 AND 100 ROUNDS AMMO IN ENVIRONMENTAL TEST CHAMBER FOR 14 HOURS AT 100 DEGREE F. AND 85 PERCENT HUMIDITY.
- # 2 TOOK GUN A -8 AND 20 ROUNDS OF AMMO OUT OF ENVIRONMENTAL TEST CHAMBER TO THE SHOOTING ROOM AND SHOT 20 ROUNDS.

LOADING ONE ROUND IN CHAMBER AND THREE IN THE MAGAZINE.

CYCLED SAFETY EVERY FOURTH ROUNDS.

PUT GUN A-8 BACK IN ENVIRONMENAL TEST CHAMBER FOR 2 HOURS.

3 AFTER 2 HOURS TOOK GUN A-8 AND 20 ROUNDS AMMO OUT OF ENVIRONMENAL TEST CHAMBER TO SHOOTING ROOM AND SHOT 20 ROUNDS.

LOADING ONE ROUND IN CHAMBER AND THREE IN THE MAGAZINE.

CYCLED SAFETY EVERY FOURTH ROUNDS.

PUT GUN A-8 BACK IN ENVIRONMENAL TEST CHAMBER FOR 2 HOURS.

4 AFTER 2 HOURS TOOK GUN A-8 AND 20 ROUNDS AMMO OUT OF ENVIRONMENAL TEST CHAMBER TO SHOOTING ROOM AND SHOT 20 ROUNDS.

LOADING ONE ROUND IN CHAMBER AND THREE IN THE MAGAZINE.

CYCLED SAFETY EVERY FOURTH ROUNDS.

PUT GUN A-8 BACK IN ENVIRONMENAL TEST CHAMBER FOR 2 HOURS.

5 AFTER 2 HOURS TOOK GUN A-8 AND 20 ROUNDS AMMO OUT OF ENVIRONMENAL TEST CHAMBER TO SHOOTING ROOM AND SHOT 20 ROUNDS.

LOADING ONE ROUND IN CHAMBER AND THREE IN THE MAGAZINE.

CYCLED SAFETY EVERY FOURTH ROUNDS.

PUT GUN A-8 BACK IN ENVIRONMENAL TEST CHAMBER FOR 2 HOURS.

6 AFTER 2 HOURS TOOK GUN A-8 AND 20 ROUNDS AMMO OUT OF ENVIRONMENAL TEST CHAMBER TO SHOOTING ROOM AND SHOT 20 ROUNDS.

LOADING ONE ROUND IN CHAMBER AND THREE IN THE MAGAZINE CYCLED SAFETY EVERY FOURTH ROUNDS.

7 CLEANED AND INSPECTED (QK)

MALFUNCTIONS 0

GUN#A-8 SHOOTER: SW SERIAL#71136315

CAL:300 WIN MAG

M/710 MAGNUM DAT #1 HEAT AND HUMIDITY TEST

TLW1216AL PROJECT #241314

ET22372