

GUN # A1 THRU A4
SHOOTER
CAL .30-06 SPRG

M/ 710 EXTRUDED RECEIVER
20 RD SHOULDER FIRE FUNCTION TEST

TLW 1530 O
PROJECT # 241230

DATE : 8/2/04		ROUND LEVEL-	
MALFUNCTIONS		MALFUNCTIONS	
A-1	30-06 SPRG	Jeff WADE	
1		51	
2		52	
3		53	
4		54	
5		55	
6		56	
7		57	
8		58	
9		59	
10		60	
11		61	A-4 30-06 SPRG Philip Reeder
12		62	
13		63	
14		64	
15		65	
16		66	
17		67	
18		68	
19		69	
20		70	
21	A-2	71	MARK HAMMOND
22	30-06 SPRG	72	
23		73	
24		74	
25		75	
26		76	
27		77	
28		78	
29		79	
30		80	
31		81	
32		82	
33		83	
34		84	
35		85	
36		86	
37		87	
38		88	
39		89	
40		90	
41	A-3	91	STEVE WADE
42	30-06 SPRG	92	
43		93	
44		94	
45		95	
46		96	
47		97	
48		98	
49		99	
50		100	

ROUNDS AFTER__

ET22753

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 EXTRUDED RECEIVER

Project: 241230

Rifle: A-2

TLW #: TLW1530

Date: 8 / 16 / 04Inspector: SWRound Level: 241

- ☒ Measure Headspace Min +.003
- ☒ Sear Engagement: 1st. .0273 2nd. .0272 3rd. .0271 Ave. .0270 spec. .020" to .025" 83
- ☐ Reset Sear Engagement if Required: 1st. _____ 2nd. _____ 3rd. _____ Ave. _____
- ☒ Trigger Pull: 1st. 5.147 2nd. 5.226 3rd. 5.117 Ave. 5.163 spec. 4 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1st. _____ 2nd. _____ 3rd. _____ Ave. _____
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: locking lugs normal wear
- ☐ Inspect stock for any signs of cracking or other failure. OK
- ☐ Other items of note: _____
- _____
- _____
- _____

TLW1216

Remington Confidential

ET22754