

CONFIDENTIAL

Remington Arms Company Inc.  
 Research & Development Technical Center  
 315 West Ring Road  
 Elizabethtown, KY 42701

## Clean & Inspect Checklist

Model: 710 EXTRUDED RECEIVER

Project: 241230

Rifle: A 8

TLW #: TLW1530

Date: 7 / 29 / 04Inspector: B LeeRound Level: 741

- ☒ Measure Headspace min+.003
- ☒ Sear Engagement: 1<sup>st</sup>. .0248 2<sup>nd</sup>. .0251 3<sup>rd</sup>. .0249 Ave. .02493 spec- .020" to .025" 83
- ☐ Reset Sear Engagement if Required: 1<sup>st</sup>. \_\_\_\_\_ 2<sup>nd</sup>. \_\_\_\_\_ 3<sup>rd</sup>. \_\_\_\_\_ Ave. \_\_\_\_\_
- ☒ Trigger Pull: 1<sup>st</sup>. 4.105 2<sup>nd</sup>. 4.231 3<sup>rd</sup>. 4.311 Ave. 4.2156 spec- 4 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1<sup>st</sup>. \_\_\_\_\_ 2<sup>nd</sup>. \_\_\_\_\_ 3<sup>rd</sup>. \_\_\_\_\_ Ave. \_\_\_\_\_
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: OK
- ☐ Inspect stock for any signs of cracking or other failure. OK
- ☐ Other items of note: \_\_\_\_\_
- \_\_\_\_\_
- \_\_\_\_\_
- \_\_\_\_\_

TLW1216

Remington Confidential

ET22899