

CONFIDENTIAL

Remington Arms Company Inc.  
Research & Development Technical Center  
315 West Ring Road  
Elizabethtown, KY 42701

## Clean & Inspect Checklist

Model: 710 EXTRUDED RECEIVER

Project: 241230

Rifle: A-11

TLW #: TLW1530

Date: 9 / 2 / 04Inspector: SWRound Level: 1740

- ☒ Measure Headspace Min +.002
- ☒ Sear Engagement: 1<sup>st</sup>. .0341 2<sup>nd</sup>. .0342 3<sup>rd</sup>. .0340 Ave. .0341 spec. .020" to .025" 83
- ☐ Reset Sear Engagement if Required: 1<sup>st</sup>. \_\_\_\_\_ 2<sup>nd</sup>. \_\_\_\_\_ 3<sup>rd</sup>. \_\_\_\_\_ Ave. \_\_\_\_\_
- ☒ Trigger Pull: 1<sup>st</sup>. 4.915 2<sup>nd</sup>. 4.952 3<sup>rd</sup>. 5.074 Ave. 4.980 spec. 4 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1<sup>st</sup>. \_\_\_\_\_ 2<sup>nd</sup>. \_\_\_\_\_ 3<sup>rd</sup>. \_\_\_\_\_ Ave. \_\_\_\_\_
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: locking lugs normal wear, bolt stop little wear
- ☒ Inspect stock for any signs of cracking or other failure. Stock cracked - no worse Photo taken
- ☒ Other items of note: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

TLW1216

Remington Confidential

ET22962