

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 EXTRUDED RECEIVER

Project: 241230

Rifle: A-12

TLW #: TLW1530

Date: 9 / 1 / 04Inspector: SWRound Level: 1221

- ☒ Measure Headspace Min +.002
- ☒ Sear Engagement: 1st .0366 2nd .0358 3rd .0360 Ave. .03593 spec. .020" to .025" 83
- ☐ Reset Sear Engagement if Required: 1st _____ 2nd _____ 3rd _____ Ave. _____
- ☒ Trigger Pull: 1st 4.589 2nd 4.520 3rd 4.544 Ave. 4.551 spec. 4 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1st _____ 2nd _____ 3rd _____ Ave. _____
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: locking lugs normal wear, bolt stop very little wear.
- ☒ Inspect stock for any signs of cracking or other failure. "Normal" 45° cracks both sides equal or 90% through upper wall (typical of these stocks)
- ☒ Other items of note: _____
- _____
- _____
- _____

TLW1216

Remington Confidential

ET22985