

RIFLE # A-13
S.N. 71163351
CAL. 300 WIN MAG

M/710 EXTRUDED RECEIVER D.A.T.

PROJECT: #
TLW: # 1530

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START -		TOTAL RDS.
				RDS. FIRED		
B.Lee	7-12-04	Initial Headspace	Min 1.004			
B.Lee	7-13-04	Proof	Min 1.004			
B.Lee	7-13-04	Re-measure Headspace	Min 1.004			
B.Lee	7-13-04	Indents	.019-.019-.018 Avg. .0186			
SW	7-14-04	Engagement	See data sheet			
SW	7-15-04	Sear Firing Pin Head Engagement	See data sheet			
SW	7-15-04	Trigger Pull	See data sheet			
B.L	7-15-04	Safety on/off Force	See data sheet			
B.L	7-15-04	Bolt opening/closing force	See data sheet			
SW	7-16-04	Sear Lift	See data sheet			
BL	8-5-04	200 Rd Basic Jack Function Test		100		101
BL	8-10-04	200 Rd Basic Jack Function Test		100		201
JS	8-10-04	Receiver Modified	Machined chamber to aid in feeding. <i>Qm</i>			
SW/JS	8/10/04	Shoulder Function Test	0 min. Penetration			
BL/JS	8/10/04	Accuracy		20		221
SW	8/10/04	Clean + Insert	OK Handoperated Min 1.005	20		241
SW/JS	8/30/04	Suzuki Juv-off	Pass			
SW/JS	8/30/04	Suzuki Rotation	Pass (Broken tang off insert)			
SW/JS	8/30/04	Suzuki Drop	Pass			
SW	9/1/04		Took insert from A-7			
SW/JS	9-2-04	Extended Juv-off	18" Pass			
SW/JS	9-2-04	Extended Juv-off	34" Pass			
SW/JS	9-2-04	Extended Juv-off	36" Pass			
SW/JS	9/2/04	Extended Juv-off	48" Pass (Broken tang off insert)			
SW/JS	9/3/04	Extended Rotation	Took insert from A-14, Put in A-13			
SW/JS	9-3-04	Extended Drop	Broken Stock			
SW/JS	9-3-04	Extended Drop	Replaced stock from A-14			
SW/JS	9-3-04	Extended Drop	72" Pass Broken Tang off insert TLW1530AD			
SW/JS	9-3-04	Extended Drop	Took insert from A-10, Put in A-13			
SW/JS	9-3-04	Extended Drop	96" FAIL			
SW	9/8/04	Put insert from A-1 into A-13	Broken Insert			
SW	10/10/04	Safety Operation (Suzuki)	PASS (See Note)			
SW	10/10/04	40lb. Trigger Pull Test	(Remington) PASS			

Note: Stripped Engagement screw in Housing.
Pushing trigger from rear of trigger forward

DAILY DATA SHEET

Remington Arms Confidential

Page 1

ET22989