

D-41-6

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

Remington

REMINGTON

PETERS

REMINGTON

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY"

RECEIVED

FEB 7 1980

J. A. STEKL

TO:

J. H. GHISNALL
BRIDGEPORT, CONN.

FROM:

D. J. SANITA

Model 600 Remington Rifle 71789
Repair Order R 31624-600

Dear Jack:

We have completed our examination of the above Model 600, which was returned to us by Snapply ServiSenter.

For completion of your files, we are attaching the gun examination report and customer's correspondence.

There were no pictures taken of the gun.

Due to the customer's reference to a personal injury, we will hold the above and await your reply as to its disposition.

Best Regards,

D. J. Sanita

D. J. Sanita:tc
attach.

Supervisor, Arms Service Division

PLAINTIFF'S
EXHIBIT

3060

AL 0022719

1 of 4

Snapply ServiSenter
(Michael Harvey)

A

Kalispell, Mont.
Nov. 3, 1979.

Remington Arms Co.

Dear Sir:

The gun discharged accidentally
in the process of unloading.
The bolt was open and the shell
showing when it discharged, the
butt coming back and hitting
me in the face, also powder burns
on the face. Haven't felt safe
with this gun since.

Sincerely,
Michael Harvey
3005 East Hills Rd.
Kalispell, Mont. 59901

AL 0022720

A

SPEED MESSAGE

TO REMINGTON ARMS COMPANY
Arms Service Division
Elion
New York 13357

FROM Snappy ServiSenter

1400 HIWAY 2 EAST — PHONE 406-257-7525

KALISPELL, MONTANA 59901

Attn: Jim Stekl

SUBJECT Warranty Repair of Remington Model 600, serial # 71789

DATE November 19, 1979

Dear Mr. Stekl:

Please find enclosed subject firearm which I am returning for my customer, Mr. Michael Harvey of Kalispell, Montana. Mr. Harvey returned this firearm to me recently, and asked that I return the firearm to you for inspection and repair of the hammer, sear, and safety assembly. Mr. Harvey feels that this firearm is one of those to which the Model 600 recall applies. I have confirmed this.

Mr. Harvey had a bad experience with this firearm, when it accidentally discharged as he was unloading the rifle. I have enclosed a note from Mr. Harvey.

Please repair this firearm under warranty, thoroughly function check and test fire, and return at your very earliest convenience to us at the above address.

Thankyou for your attention to this matter.

Sincerely,

W. J. LUPTON

SIGNED

P.1 YES GUN EXAMINATION REPORT NUMBER: 135 MODEL: 600
 GENERAL CONDITION: POOR R #: 31524
 OUTSIDE WORK: SCOPE SCREW + REAR SCREW DATE: 11-29-79
REMOVED FROM: 1400 HWY 2 EAST
 FIRED AMMO TYPE: NOT KNOWN KALISPELL HWY 500
 & CONDITION: OK GUN #: 71789
 PROOF: REP INSP.: N TEST: 32 CODE: OK=9-63
 HEADING: OK GA./CAL.: 243
 BREACH OPENING: OK CHECKED BY: M-HARDY
 RECOIL SHOULDERS: OK APPROVED: JDH 12/21/79
 CHAMBER: DIRTY APPROVED: JS 12/21/79
 TEST: OK APPROVED: EB 12-21-79
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: JS 12-21-79

STOCK BEAT UP. BRIGHT METAL ON BBL
BOLT RUSTY RIFLE DIRTY CHAMBER RUSTY

COMPLAINT: DISCHARGED ACCIDENTALLY IN PROCESS
OF UNLOADING - "When bolt open & shell showing"

INCIDENT: for customer

COMMENTS: Gun passed test test. No evidence of gun damage,
in area of mag box. Incident described by customer is
mechanically impossible in this gun.

AL 0022722

Gun involved in recall program - Repair at no charge