COPIES TO: C.K. DAVIS D.E. CARPENTER W.O. REISINGER B.E. STRADER F.K. CRAIG G.O. CLIFFORD M.R. WARDEN G.E. PINCKNEY A.L. FRENCH W.L. CLAY W.F.H. MATTLAGE BRIDGEPORT.	H.K. FAULKNER W.H. DAVIS H.A. BROWN R.H. GRACE H.J. HACKMAN (6) D.S. FOOTE D.E. MILLER S.W. ROSE R.A. WILLIAMSON A.J. BROWN R.E. WRIGHT
TOTAL JUSTIFIED COMPLAINTS	
SEPTEMBER 1948	<i>33</i> 5
SEPTEMBER 1947	113
TO DATE 1948	2207
TO DATE 1947	1103
FOR 12 MONTHS ENDING SEPTEMBER 30, 1948 FOR 12 MONTHS ENDING SEPTEMBER 30, 1947	2602 1393
LAST 12 MONTHS RUNNING AVERAGE	216
LAST 12 MONTHS RUNNING AVERAGE (1 YEAR AGO)	116
LAST 12 MONTHS RUNNING AVERAGE (SIX MONTHS AGO)	172
COMPLAINTS ON GUNS PRODUCED WITHIN ONE YEAR	•
CURRENT MONTH SEPTEMBER 1948	289
APRIL 1948	157
SEPTEMBER 1947	99
SEPTEMBER 1946	0
FOR 12 MONTHS ENDING SEPTEMBER 30, 1948	2193
LAST 12 MONTHS RUNNING AVERAGE ON GUNS PRODUCED WITHIN ONE YEAR.	182

GOMPLAINTS ON FIREARMS FOR MONTH ENDED SEPTEMBER 30, 1948.

	PRODUCED ONE	WITHIN YEAR	TOTAL
MODEL 81# # JACKET HEAD LOOSE		1	11
O FAILS TO EXTRACT (EXTRACTOR OUT OF ADJUSTME O FAILS TO EJECT	ENT)	3	2 3
O MAGAZINE SPRING BROKEN O MAGAZINE FOLLOWER BINDS		3	2 3 3
X ROUGH CHAMBER) a	1
X INDICATOR SPRING OUT OF POSITION		2	Ş
DEFECTIVE BARREL X BOLT OPENS HARD	,	1	1
X TANG SCREW POORLY FITTED	•	77-	32
SPORTSMAN - 12 GA.	•	·	
FIRING PIN RETAINING PIN BROKEN O TRIGGER BINDS		1	. 1
STOCK BROKEN O JAMS (FEEDS UP)			1
BREECH BLOCK CRACKED	•	1	<u> </u>
		,	, , , , , , , , , , , , , , , , , , ,
SPORTSMAN - 16 GA. O STEMS CHAMBER		•	
			€
SPORTSMAN - 20 GA. CARRIER DOG OUT OF ADJUSTMENT		1	1
BOLT BINDS O FORE-END SETS BARREL TOO FAR OUT	,	1	
		2	3
MODEL 11 - 12 GA. O SHELLS STEM CHAMBER		1	1 .
O CARRIER LATCH OUT OF ADJUSTMENT N BAR EL WALL THIN		1	· 1
X SEAM IN BARREL		1	1
STOCK SPLIT FORE-IND SPLIT		į	ż
X RIB NOT LINED WITH BARREL	•		·

SHEET NO. 2

•		PRODUCED WITHIN	TOTAL
MOD O X	EL 11 - 16 GA. EXTRACTOR OUT OF ADJUSTMENT OPERATING SLIDE FILED OUT OF SHAPE		1 1 2
MODI	SHELLS STEM CHAMBER		
MODI	EL_121		
	FIRING PIN BROKEN	1	1
X	FIRING PIN STRIKES INSIDE RIM STEMS CHAMBER	ji Ji	24)1
ŏ	TAKES MAX. PLUG	1	2
0	FAILS TO EJECT	3	1
0	FAILS TO EXTRACT	1	1
X	ACTION BAR MACHINED WRONG	•	1
X	FIRING PIN NOT UP TO STANDARD FACE OF BLOCK ROUGH	1	1
ô	STEMS RETAINER	, .	2
. •	ACTION DOES NOT LOCK UP	วั	โ
X	JAMS (SHELLS CATCH BY CARTRIDGE STOP)	. 1	1
0	BLOCK UNEVEN AT FACE	1	. 1
0	BOLT PULLS OUT	I.	1
X	BARREL PITTED		1
	WEAK CARRIER DOG SPRING HAMMER ROD GUIDE BENT	. I	1
	TAPAEN NOO GOTOE DENT	25	28
			 -
	EL 141		_
0	SEAR AND SEAR LOCK OUT OF ADJUSTMENT	2	2
0	JARS OFF FAILS TO EXTRACT	1 2	2
0	FEEDING PLUG GOES BY CARTRIDGE STOP (JAMS)		1
×	CARTRIDGE WAYS IN BAR NOT TO STANDARD	•	i
ô	ACTION BINDS	9	i i
	FIRING PIN EXTENSION LOOSE FROM FIRING PIN	j	2
	ACTION BAR LOCK WORN	3	1
•	TAKES MAX PLUG		-13
		7	13
MODI	EL_241		
δ	FATLS TO DISCONNECT	3	3
X	POOR NOTCH ON FIRING PIN	<u>6</u>	2
X 0 0 X X	FAILS TO EJECT	36 7	798117211
Ô	FAILS TO EXTRACT	1	Ĭ
Ş	SIGHTS OUT OF LINE NOT ACCURATE #MUZZLE UPSET)	a) %
ô	CARTRIDGE STOP OUT OF ADJUSTMENT	. 3 2	.5
•	STOCK CHECKED OR BROKEN	ī	ī
0	BARREL TAKE UP IS LOOSE	, \$	1
X	BARREL LOOSE	2	2
	(CONTINUED)		_

•		
	PRODUCED WITHIN	700
MODEL 241 CONTINUED	ONE YEAR	TOTAL
O STEMS CHAMBER O FAILS TO COCK	1 7	7
SAFETY OPERATES HARD		
· •	35	40 .
MODEL 31 - 12 GA. O SHELLS STEM CHAMBER		•
O TRIGGER LOCK OUT OF ADJUSTMENT	1	1
O FAILS TO EJECT FORE-END BROKEN	1	1
BARREL DAMAGED AT MUZZLE	: i	Ī
BARREL ASSEMBLED HARD BURST BARREL (THIN WALL)	1	1
	5	8
MODEL 31 - 16 GA.		•
SEAM IN BARREL	-1	
	· • • •	•
MODEL 31 - 20 GA. X TRIGGER BINDS	1	1
		- -
MODEL 37		•
X TRIGGER PULL NOT PROPERLY ADJUSTED X FAILS TO COCK	1	1
ELEVATION PLATE DAMAGED	•	į
RECEIVER HAS SHARP EDGE NEAR BOLT HANDLE		-1 -
MODEL 510		•
BOLT HANDLE BROKEN		1
O FAILS TO EJECT N BARREL BENT	2	2
X EJECTOR TOO LOW	į	
N SIGHTS NOT PROPERLY ALIGNED DEFECTIVE BARREL	1	1 1.
FAULTY ACTION	i	į
BROKEN EJECTOR Bolt binds on sear	1	1
	8	10
MODEL 511	_	
STOCK CHECKED N NOT ACCURATE	1	1 2
N FAILS TO EJECT	· 2	1 2 2 2 1
X CARTRIDGE STEMS CHAMBER	1	2 1
X BARREL NOT STRAIGHT X CARTRIDGE STEMS CHAMBER O BOLTS PULL OUT # BOLT AND SEAR DAMAGED O THREADS IN PEEP SIGHT HOLE IN RECEIVER STRIP	3	3
	PPED	1
MAGAZINE FOLLOWER BROKEN	14	1-14-
	1 7	, 7

SHEET NO. 4

		PRODUCED WITHIN	
		ONE YEAR	TOTAL
MODE	<u>L 512</u> Cartridge retainer out of adjustment	8	Q
ŏ	FAILS TO FEED	8 3 2 2 5	932 251
	STOCK CHECKED	ž	Ş
^	BOLT HANDLE BROKEN	2	2
O N	FAILS TO EJECT NOT ACCURATE	}	3
X	CARTRIDGE STOP PLUNGER BINDS	•	i
	SEAR BROKEN	3	3
X,	BARREL BENT	3 12 2 3	32 32 32 32
# N	BOLT PULLS OUT	12	13
Ö	NOT ACCURATE (SIGHTS OUT OF LINE) DROP SHELLS	4	3
	MAGAZINE RING THREAD BAD	Ź	Ź
	BOLT HANDLE LOOSE	_	1
	JAMS BOLT BINDS		1
	TAKE DOWN SCREW HOLE IN RECEIVER TOO LARGE	i	i
	CARRIER BINDS ON CARTRIDGE STOP PLUNGER	<u> </u>	1
		49	53
MODE	L 513	•	-
HOUL	STOCK CHECKED	1	1
0	FAILS TO EJECT	1	2
X	POOR TRIGGER PULL	1	. !
X	KEY HOLES DEFECTIVE BOLT HANDLE		. 1
	SIGHT SCREW BROKEN	. 1	i
		5	7
	·		
MODE	<u>514</u> Trigger bent	O .	ο.
â	SAFETY OUT OF ADJUSTMENT	· }	í
••	BOLT HANDLE BROKEN	1	1
X	POOR RIFLEING	2	2
X	BARREL BENT	3	? .
X	LOOSE BOLT HANDLE POOR FINISH	i	i
^	NOT ACCURATE	• •	1
	BOLT COMPLETE MISSING	1	-2
		20	20
MODE	L 521		•
تحتن	STOCK CHECKED	Ž	2
_	BOLT HANDLE BROKEN	· 3	3
0	THREADS STRIPPED ON REAR SIGHT ELEVATING SCRI	LW I	1
v	REAR SIGHT MISSING	i	i
	SEAR AND BOLT DAMAGED	1	1
•	TRIGGER AND SPRING PLUNGER MISSING	1	1
X	BARREL BENT	-14	-11
		, , ,	- V

SHEET NO. 5

•	PRODUCED WITHIN	TOTAL
MODEL 550-1		TOTAL
O EXTRACTOR OUT OF ADJUSTMENT	. 1	1
O FAILS TO FEED	<u>i</u>).
X ROUGH ACTION	i	i
X NOT ACCURATE	i	1
X JAMS (INSERT ROUGH)	7	7
O FAILS TO EJECT	13	13
O FAILS TO CONNECT	2	13 2 2
O FAILS TO EXTRACT	· Ž	2
O MISFIRES	1	1
CONNECTOR SPRING WEAK	3	3
X BOLT BINDS	7	1
X CONNECTOR PIN OUT OF POSITION	1	1
STOCK SPLIT AT TIP	1	1
THREADS IN MAGAZINE RING HOLE IN BARREL	POOR 2	2
SHELLS SWELL		
DEFECTIVE BOLT FIRING PIN DAMAGED		
CARRIER AND CARTRIDGE STOP BINDS		
BROKEN SAFETY	· i	į
INNER MAGAZINE TUBE FAILS TO CLOSE FULL I	MAG. i	i
BARREL BENT	i	i
	77	47-
MODEL 721	·	•
# STOCK CRACKED AT GRIP	11	11
X . BOLT CLOSES HARD	3	3
BOLT DAMAGED	1	Ĭ
DEFECTIVE BOLT	4	4
O FAILS TO EXTRACT	1	1
BOLT HANDLE CRACKED	Ţ	1
FAULTY SAFETY		Ţ
TRIGGER BINDS	1	1
MAGAZINE FOLLOWER BINDS MAGAZINE OUT OF ADJUSTMENT	1	Ţ
MAGAZINE OUT OF AUJUSTINENT	سياود	- Ageline
	25	4 9
MODEL 722		
SAFETY AND TRIGGER OUT OF ADJUSTMENT	1	1

CORRECTED IN RECENT PRODUCTION OVERSIGHT IN INSPECTION

CLOSE ADJUSTMENT NOT SHOWING UP IN FACTORY TEST RESULTING IN MALFUNCTION THRU USAGE.

NOT COVERED BY INSPECTION

COMPLAINTS RECEIVED DURING SEPTEMBER 1948 - ON GUNS PRODUCED IN THE FOLLOWING YEARS.

MODEL	1948	1947	1946_	1945	MISC.& PARTS
MODEL 81 SPORTSMAN - 12 GA.	10 3	7	15		
SPORTSMAN - 16 GA. SPORTSMAN - 20 GA.	•	2	1	•	
MODEL 11 - 12 GA. MODEL 11 - 16 GA. MODEL 11 - 20 GA.	f	1	1		
MODEL 121 MODEL 141	18	7	3		
MODEL 241 MODEL 31 - 12 GA.	5 32 5	3	5		
MODEL 31 - 16 GA. MODEL 31 - 20 GA. MODEL 37	1	•	•		
MODEL 510 MODEL 511	6 9	2 2 5	2		
MODEL 512 MODEL 513	35	14 1	4 2		•
MODEL 514 MODEL 521	19 42 24	1 2			
MODEL 750-1 MODEL 721 MODEL 722	24 1				
•					

H.E.WEEKS:FH 10/6/48.