DEGETVED APRI 9 1950 W. L. CLAY CC: G.H.Calhoun B.F.H.Wattlage W.L.Clay H.J.Hackman

April 18, 1950

70:

H. K. Faulkner

FROM:

S. Y. MYIS

SUBJECT:

MODEL 721 RECZIVER

This is in regard to recent memorendum from Mr. Mattlage with comments pertaining to customer complaint on failures to eject loaded rounds. This characteristic was described at the Products Committee meeting of January 27th and was also included in the proposed agenda forwarded to G. M. Calhoun and W. L. Clay under date of December 29, 1949. In addition, it was included in the final agenda as used at the Products Committee meeting and identified as Item G-4 (b) as follows:

ainor change has been suggested in the way of an added machining cut on the Roceivers which gives additional elsewance and improves ejection. This was recognised during production pilot testing and has subsequently been suggested by sustaners. To accomplish this change will require a tooling cost estimated at \$500, along with the additional direct later for the extra milling operation which is expected to cost 1; to 1-1/4# additional per gun.

Apparently the decision for adopting this improvement was not included in the Minutes of the meeting, although favorable action was taken and the design was changed accordingly. It is understood that the improvement is now in effect, however, expect that the complaint involves guns of darlier manufacture. We also believe that the new Operations Committee procedure as now in effect will give greater assurance of action on these items being reported.

S. W. Alvis
Arms Technical Division

SILLI