

G-55-REM

DON'T SAY IT—WRITE IT

To W. E. LeekDATE 5-7-52FROM C. J. TheriaultMODEL 721 - POWDER METAL TRIGGER

THREE
Two of the above triggers have been dry cycled 10,000 rds. each, with no excessive wear or brinelling. One trigger was also subjected to a -20°F. cold test. No breakages occurred in actual firing, however, the coloring changed. It was at first believed that the chemical reaction of the dry ice could have caused this condition, however, after placing two triggers in an air-tight container, the test was repeated and discoloring was still apparent.

C. J. Theriault
Supervisor, Testing Unit
Arms Research & Development Division

CJT:LF

CC: S.M. Alvis
M.H. Volker

FORETHOUGHT IN PLANNING HELPS TO ELIMINATE INJURIES