

GUN # A-8
SERIAL # 71159113
CAL: 30-06 SPRG

M770 FIRE CONTROL SAFETY DETENT DESIGN CHANGE PROPOSAL

TRACKING # TLW 1463
PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS FIRED	AT START-0 TOTAL RDS.
SW	6/2/04	Out of box initial	Safety detent function check and inspection		
SW	6/2/04	Perform 10 complete cycles from on site to five	TLW1463A		
SW	6/2/04	Measure safety ON and OFF forces	TLW1463B		
SW	"	Headspace before Proof	Min +1.003		
SW	"	Proof Round	OK		
SW	"	Headspace After Proof	Min +1.003		
SW	6/3/04	Live Fire Test	100% Hit 0 - Multifunctions	100	101
SW	6/4/04	Cleaned			
SW	6/4/04	Headspace	Min +1.003		
SW	6/5/04	Setup for Semi Inv-off			
SW	6/5/04	Semi Inv-off Test Pass	TLW1463D		
SW	6/6/04	Semi Rotation Test Pass	TLW1463E		
SW	6/6/04	Semi Drop Test Failed	TLW1463F		
SW	"	"	Cracked Insert		
SW	6/7/04	Semi Drop	Failed, Barrel Horizontal, Rotation of stock up.		
SW	"	"	Gun fired as result of an override and the insert was cracked due to previous drops.		
SW	6/8/04	Setup Live control	Take insert from A-11 and put five control parts from A-8 into five control		
SW	"	"	A-11. Put five control in A-8, and set engagement with trigger pull		
SW	6/8/04	Semi Drop	Finish up the Drop Test		
SW/PA	6/14/04	Pictures taken of cracked fire control	Insert insert PASS		

Logform

83

ET23298