

7-1-55

Aluminum 222, 257 RPK, 320 R50

1

0

Rem 117 SF RM 1/0

80

120

Rem 100 RSP 1/60

400

240

Rem 117 SF 250

320

7/7/55

X HARD to EXTRACT FINGER COUSSES

Rem 117 SP RM 360

RM 400

RM 440

RM 480

RM 500

1  
1x  
3  
1  
X

Cannot be fingered. Bone enlarged too much.  
Test stopped 7-7-55.



7-1-55 722 257 Rbts 320/150  
 Aluminum Rb. evidence Test

|           |        |    |   |
|-----------|--------|----|---|
| Rm 117 SR | PM 43  | SD | 1 |
| Rm 117 SR | PM 120 |    | 1 |
| " " "     | PM 160 |    | 2 |
| " " "     | PM 180 |    |   |
| Rm 100 SR | PM 200 |    | 1 |
| " " "     | PM 240 |    | 3 |
| " " "     | PM 280 |    | 1 |
| " " "     | PM 320 |    | 4 |
| " " "     | PM 360 |    |   |
| Rm 117 SR | PM 400 |    | X |
| " " "     | PM 440 |    | X |
| " " "     | PM 480 |    | X |
| " " "     | PM 520 |    | X |

7/7/55

Cannot be fore-gaged. Bore enlarged too much.  
 Test stopped 7-7-55.

Will be new plug.  
 at rest

Front Case, 100 SR, 2 SR, 1 SR