

AMMUNITION		MALFUNCTIONS										REMARKS											
Shooter		No. of Rds.		Firing	Extraction	Don't Blow Back	Ejection	Locking Open	Feed from 1st Mag.	Feed from 2nd Mag.	Double Feed From Magazine	Dropped Shell	Failed to Trip Carrier Latch	Stem Carrier	High Low Rt.	Stem Chamber	Locking Up	Loading	Breakages	Replacement	Gun Failure	Adjustments	
PREVIOUS 320 RDS.		FC 370																					OK
2ND - REM 220 SP		FC 400																					OK
" " "		FC 450																					OK
" " "		FC 500																					OK
" " "		FC 550																					OK
" " "		FC 600																					OK
" " "		FC 650																					OK
" " "		FC 700																					OK
" " "		FC 750																					OK
" " "		FC 800																					OK
" " "		FC 850																					OK
" " "		FC 900																					OK
" " "		FC 950																					OK
" " "		FC 1000																					OK

DATE 3/2/57 MODEL 721 CAL. 3006 GUN NO. 195367 Sheet No. 2

DESCRIPTION OF TEST: Quality Audit Test

Total Rds. Fired _____

Total Malfunctions _____

Rate _____

REMARKS

MAX. FUNCTIONS AT 320 RDS - 1.65%

MALFUNCTIONS AT 1000 RDS - 1.5%

297-1700

DATE: 3/12/57

MODEL, 221

30.06

REF ID: A395367

⑤

DESCRIPTION OF TEST:

Quesada

ANOT

TEST

CONDITIONS OF TEST

NO. 65, 1907

[illegible][illegible]