

*Customer
Inquiries*

Beegie's Sporting Goods
133 S. Richard Street
Bedford, Pa.

January 27, 1958

Dear Mr. Beegie:

Your M/40X Trigger is being shipped by Parcel Post first class today. It is a new Trigger which has been readjusted. It is adjusted with as little engagement as will hold the rifle in a cocked position. For this reason it will be necessary to prevent accumulations of dirt or gummed oil from collecting in the mechanism. I have found that Hoppes No.9 is a useful solvent in removing these accumulations. If properly cared for the setting should last for a long time.

You will note that slave pins are used in the assembly. This is done to ease the assembly to the receiver. The slave pins are driven out by the regular pins during the assembly operation.

Let me know how you make out with this one!

Sincerely,

M. H. Walker, Supervisor
Design Section
Ilion Research Division

MHW:NL