

SHEET NO. 1

P.L.T.

Total Rds. Fired _____
Total Malfunctions _____
Rate _____

TOTAL

Total Rds. Fired _____
Total Malfunctions _____
Rate _____

[illegible]

Rate

[illegible]

SHEET NO. 1

P.L.T -

Rate

[illegible]

Along with my book OK. Take down some ground
off to avoid belt bag interference.

GUN NO. 1185 SHEET NO. 1
Total Rds. Fired _____
Total Malfunctions _____
Rate _____

[illegible]

GUN NO. 3187 SHEET NO. 1

Total Rds. Fired _____
Total Malfunctions _____
Rate _____

[illegible]

DESCRIPTION OF TEST

P.L.T-

Total Rds. Fired
Total Malfunctions
Rate

[illegible]

(5)

DATE 3-1-62 MODEL 700 CAL./GR. 222 GUN NO. 3282 SHEET NO. 1

DESCRIPTION OF TEST P.L.T. -

Total Rds. Fired _____
Total Malfunctions _____
Rate _____

AMMUNITION	Shooter	No. of Rds.	Firing	Unlock	Extract	Eject	Cock	Feed	Load	Lock	Breakage	Replacement	Gun Failure	Adjustment	REMARKS	TOTAL
R222SPSOG	V	20				"3									Extractor free	
"	V	20				"3									Remo-shell Hung under Extractor (2nd) (3rd) (5th)	
"	V	20				"3									" 2, 5, 5	
"	V	20				"3									" 2, 5, 1	
"	V	20				"2									" 2, 1	
"	V	20				"3									" 3, 1, 5, 1	
"	V	20				"1									" 3, 1, 1	
"	V	20				"2									" 1, 3, 6, 1	
"	V	20				"4									" 2, 5, 3, 1	
"	V	20				"1									" 5	
3/2/62 "	V	20													Used bolt from No. 1 gun M.H. Walker is under the impression that angulation was missed on the face of the bolt stand OK.	
TOTAL																