

W
*This is the copy of the letter
 given to you by the
 points, TX, Sons*

United States Army Instructor Group
 Athens High School (JR ROTC)
 Athens, Georgia

October 4, 1962

Attention: Capt. Lawrence S. McKensie Jr.
 Prof. of Mil. Science

Dear Captain McKensie:

Your letter of September 28, addressed to our Bridgeport Division, has been referred to the Arms Section for attention.

We regret to learn of the difficulty encountered with a Model 801 22 caliber rifle due to the rifle firing on closing of the bolt. It is important that the trigger assemblies are set up adjustment with the connectors and screws not being properly engaged.

In order to assist you, we are enclosing an insert from the Repair Manual of the M16, which will explain in detail the proper adjustment to be made to the trigger assembly. We feel certain that after you have had an opportunity to make this insert, your difficulty can be easily remedied by following the directions given.

We are also enclosing instruction folders and parts sheets for the event you desire to order any parts for these rifles.

By copy of this letter, we are notifying our representative Mr. R. G. Sherman of 2251 Highland Avenue Birmingham, Alabama, to pay you a visit the next time he is within your vicinity.

If further trouble is encountered the trigger assemblies could be removed from the arms and be forwarded to the Factory here at Ilion, N.Y., for examination and adjustment.

We trust the above information and insert will be of aid to you.

F. W. Woodrick, Jr.
 cc John Jay, Dpt
 F. E. Morgan, Dpt
 R. G. Sherman
 Rem. Div.

Cordially yours,
 REMINGTON ARMS COMPANY, Inc
J. H.
 Arms Service Division ILION NY