

Mr. Tom Wible
P. O. Box 51
Pike Road, Alabama

April 8, 1964

Dear Mr. Wible:

We received your broken connector from the M/40X rifle. A trigger assembly is being sent to you and also one for your friend who is also having trigger problems (please forward to him).

The present trigger assembly may be removed by driving the two pins out. The new assembly is installed by driving the same two pins back, or a local gunsmith can do it for you. Please send both trigger assemblies back to my attention.

The trigger is damaged when the primer ruptures (caused by high pressures). This can be remedied by seating your bullets deeper. Ruptured primers may also be caused by seating the primers too deep.

If we can be of any further service to you please feel free to contact us again.

Sincerely,

L. P. Gogol
Ilion Research Division

LPG:nl