

cc: S. M. Alvis  
H. J. Waterman

Ilion, New York  
September 4, 1964

H. J. HACKMAN

I have been having considerable accuracy difficulties caused by improper inletting of the stock in the M/600, and have asked Harold Waterman to discuss this problem with your personnel to determine what efforts are being made as to correction.

After looking over a considerable number of M/600's since they have been in production last year I don't believe I have ever seen one where the fore end wasn't touching the left side of the barrel and was advised at that time that correction would be made.

Now that we are involved in a laminated stock and a more expensive gun it would seem past due time to make this correction and effort should be made to accomplish this before manufacturing the new stocks.

Attached is a report from Harold to me regarding the above.

W. E. Leek  
Firearms Design & Development  
Ilion Research Division

WEL:T  
Attach.