

G-88

DON'T SAY IT—WRITE IT

TO W. E. LEEKDATE Oct. 1, 1964FROM V. G. DEREUSCC: S. M. ALVIS
H. J. Hackman
M. H. Walker*Taken 10/7*MODEL 600 BOLT - GAS ESCAPE HOLE

Confirming conversation, Sales has requested a letter giving the reasons for elimination of the gas hole in the Model 600 Bolt. The legal department will also have to be advised as the elimination might affect legal action in case of an injury case.

It is assumed that the testing would include the Model 700 Bolt gas escape hole and the gas escape hole in the Model 700 Receiver elimination.

If the gas escape hole is eliminated only in the Model 600 and not the Model 700, production difficulties and added inventory of parts would result.

VGD:I

THERE IS A SAFE WAY; DO IT THAT WAY