

[Handwritten signature: J. H. Burdett]
[Handwritten signature: W. N. Jones]

RECEIVED

OCT 7 1964

P. H. BURDETT

RECEIVED

OCT 7 1964

VICE PRESIDENT AND
 DIRECTOR OF PRODUCTION

cc: R.A. Williamson
 S.M. Alvis
 W.E. Beck
 R.J. Hackman
 V.G. DeRous
 A.D. Kerr
 F.T. Plunkett
 Estimate File #2512

Ilica, New York
 October 6, 1964

H. K. FAULKNER (2)
 ATTENTION: C. L. JONES

MODELS 700 AND 600 SAFETY MARKINGS FOR EXPORT

Estimates indicate an additional factory cost of ninety cents (\$.90) per gun for the proposed safety position markings.

Receiver tangs under the safety will be engraved as follows:

1. A letter "S" in the rear position indicating "Safety On".
2. A letter "F" in the front position indicating "Ready to Fire".

Estimated costs are based on these assumptions:

1. Custom Repair will unpack warehouse guns.
2. Custom Repair will engrave and paint markings.
3. Custom Repair will repack and label for warehouse.

R. A. Williamson
 Works Manager

[Handwritten signature: R. L. Hall]
 R. L. Hall, Supervisor
 Methods & Standards Section

RFKerrigan

[Large handwritten note:]
 Provided additional
 orders in memo
 of 100 are placed