

EN-3313-A 8-49

JOB TESTING + SHIPPINGNO. 5
PAGE 1 OF 1

DETAILS OF (PRESENT PROPOSED) METHOD	OPERATION	TRANSPORT	INSPECTION	DELAY	STORAGE	DISTANCE IN FEET	QUANTITY	TIME	ANALYSIS				NOTES	ACTION			
									WHAT?	WHERE?	WHEN?	HOW?		ELIMINATE	COMBINE	REQUIRE	REDESIGN
(1) <u>IN LOADING ROOM</u>	☒	☒	☒	☒	☒								WHILE AMMO IS HAND LOADED				
(2) <u>WIPE OUT BARREL</u>	☒	☒	☒	☒	☒								CLEAN CLOTH USE HOPPER IT SITS				
<u>Take to Gallery</u>	☒	☒	☒	☒	☒								26-3 PISTOLS				
<u>wait</u>	☒	☒	☒	☒	☒								FROM WHEN IT FINISHES IN USE				
<u>PROOF TEST</u>	☒	☒	☒	☒	☒								1 TEST				
<u>STAND BARREL POINT FORWARD</u>	☒	☒	☒	☒	☒								REM FROM WHEN				
<u>TAKE TO 150 YD RANGE</u>	☒	☒	☒	☒	☒												
(1) <u>A.T.</u>	☒	☒	☒	☒	☒								JUST AFTER NOON				
<u>BREVSIGHT RIFLE + WE FACTORY AND</u>	☒	☒	☒	☒	☒								SHOOT TARGETS AT 100 YD				
<u>TEST 3-5 SHOTS AROUNDS HAND</u>	☒	☒	☒	☒	☒								NOTE IN SEQUENCE SHOT IF RIFLE SHOT				
<u>PICK UP TARGETS</u>	☒	☒	☒	☒	☒								DOWN RANGE, EX FOR TARGETS				
<u>RETURN TO CUSTOMER</u>	☒	☒	☒	☒	☒												
<u>WIPE WITH HOPPER</u>	☒	☒	☒	☒	☒								SHOOTING FOR 100 YD CLEANING DONE A.M.				
<u>WIPE OUT BARREL</u>	☒	☒	☒	☒	☒								HOPPER				
<u>WIPE OFF RIFLE</u>	☒	☒	☒	☒	☒								3-36012				
<u>POLISH END OF BOLT FORM</u>	☒	☒	☒	☒	☒								WITH BRUSH 6" 36012 BRUSH				
<u>PICK UP SHIPPING TICKET</u>	☒	☒	☒	☒	☒								SHIPPING TICKET -AREE				
<u>DELIVER TO SHIPPING</u>	☒	☒	☒	☒	☒								WARD FENTON FERT, FOR FENTON				
	☒	☒	☒	☒	☒												
	☒	☒	☒	☒	☒												
	☒	☒	☒	☒	☒												
	☒	☒	☒	☒	☒												
	☒	☒	☒	☒	☒												
	☒	☒	☒	☒	☒												
	☒	☒	☒	☒	☒												
	☒	☒	☒	☒	☒												
	☒	☒	☒	☒	☒												
	☒	☒	☒	☒	☒												
	☒	☒	☒	☒	☒												
	☒	☒	☒	☒	☒												
	☒	☒	☒	☒	☒												
	☒	☒	☒	☒	☒												