

Visual observations

Jim Barber

Std Sear vs P.M. Sear

10/22/65

PM Chromed sears

50,000 cycles or dry cycle

Sear cam surface

Shiny spots but no wear (appreciable)

Sear connector surface

Shiny spots but no wear. (appreciable)

Connectors in contact with above,

Shiny at contact points some wear
very slight deformation of top surface,

Std sears 50,000 cycles or dry cycle machine

Sear cam surface

Shiny spots but no wear (appreciable)

Sear connector surface

Shiny & rounded over from contact with cam

Connectors in contact with above,

shiny at contact points - some wear.
deformation of top surface from contact with sear