REMINGTON ARMS COMPANY, INC.

Remington WPD PETERS

"CONFINE YOUR LETTER TO ONE SUBJECT CHAPT'S

DROP TEST PROCEDURE

MEASUREMENT and TEST LAB

- I. Trigger Pull and Firing Pin Indent
 - A. Take five samples.
- II. Safety Mechanism Shock Test
 - A. Drop gun ten inches on solid wood surface with safety "ON"
 - 1. Butt down
 - 2. Muzzle down
 - Topside down -
 - 4. Bottom down
 - B. The Trigger shall be tried after each drop to determine whether the safety has released any mechanism which may allow firing
 - C. Three drops per position.

III. Jar-Off Test

- A. Drop gun ten inches on solid wood surface with safety "OFF"
 - 1. Butt down
 - 2. Muzzle down
 - 3. Topside down
 - 4. Bottomside down
- B. The Trigger shall be tried after each drop to determine whether : the safety has released any mechanism which may allow firing.
- C. Three drops per position.

AAH:

DROP TEST PROCEDURE - Measurement. & Test Lab

IV. Safety Operations Test

١.

- A. This test is for testing the safety mechanism.
 - 1. Cock gun
 - 2. Put Safety "ON"
 - Try Trigger
 - 4. Release the Safety
 - 5. · Pull Trigger
 - 6. Record if Trigger functions with Safety on
 - 7. Record if Firing Pin fell when Trigger was pulled
- B. Make 50 trials.

V. Safety Mechanism Shock Test

- A. Drop gun "waist height" on solid wood surface with safety "ON
 - 1. Butt down
 - Muzzle down
 - 3. Topside down
 - 4. Bottomside down
- B. The Trigger shall be tried after each drop to determine whether the Safety has released any mechanism which may allow firing.
- C. Three drops per position.

VI. <u>Jar Off Test</u>

- A. Drop gun "waist heigh:" on solid wood surface with safety "OFF
 - 1. Butt down
 - 2. Muzzle down
 - 3. Topside down
 - 4. Bottomside down
- B. Trigger shall be tried after each drop to determine whether the safety has released any mechanism which may allow firing.
- C. Three drops per position.

VII. Gun Function Check

- A. Trigger pull
- B. Firing pin indent
- C. Take sample of five.

AAH:T