

MELBOURNE



# BOUSTEAD WOOD PTY. LTD.

407 CITY ROAD, SOUTH MELBOURNE • PHONE ★ 887501  
BOX No. 120 P.O. SOUTH MELBOURNE, VICTORIA, 3205  
CABLE AND TELEGRAPHIC ADDRESS: "WINWOOD" MELBOURNE

BRANCH OFFICES: BRISBANE, SYDNEY, ADELAIDE, PERTH  
AND AT: WELLINGTON, AUCKLAND, CHRISTCHURCH, LONDON  
REGISTERED OFFICE: 407 CITY ROAD, SOUTH MELBOURNE


BRM:MC  
1742

12th June 1968

Remington Arms Co. Inc.,  
Bridgeport,  
CONNECTICUT 06602, U.S.A.

Attention: Mr. Peter J. Rosendahl

Gentlemen,



Replying to your letter dated 8th May concerning  
the safety tests conducted on firearms by our Customs Department,  
we advise as follows:-

Section 2 (a) is correctly interpreted by Ilion.

The gun is struck on various parts including  
the barrel and cocking piece.

Since the original report of failure of the model  
700 rifles in this test, the method of testing has been refined,  
and we do not anticipate any more problems with Section 2 (a).

Section 2 (b) was recently deleted.

A further modification to the safety standard  
was made under Section 5.

The method of hardness testing previously set down,  
now applies only to case hardened parts. All through hardened  
parts must show a hardness of 450 D.P.N. using a 30 Kg. Load.

To sum up with the change in the standards, more  
refined and intelligent methods of testing are being used, and we  
do not expect any problems with REMINGTON firearms, although there  
may be occasional guns or rifles which fail to meet this specified  
hardness test, as although a model may have passed several times,  
the Customs keep on checking and re-checking the same model as long  
as it is being imported.

Yours faithfully,  
BOUSTEAD WOOD PTY. LTD.

*B. R. Martin*  
.....  
BTR. MARTIN - DIRECTOR

ALSO AT BRISBANE, SYDNEY, ADELAIDE, PERTH, (W.A.) AND LONDON