

APPENDIX LIMITED DISTRIBUTION

Assembly Methods

	<u>Remington</u>	<u>Winchester</u>
copper braze:	bolt handle to bolt body 700, 660	bolt handle to bolt body 770, 670
	bolt head to bolt body 700, 660	
spot welded:		folded magazine box assembly
threaded permanent:	barrel to receiver, 700, 660	barrel to receiver, 770, 670
		firing pin sleeve to firing pin (also drive-loc pinned)
threaded removable:	front and rear sights to barrel	front and rear sights to barrel
	bolt plug to bolt body	bolt sleeve to bolt body
	receiver assembly to stock	receiver assembly to stock
pinned:	firing pin tip to firing pin	