

Rev. 2-15-61

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 660
GENERAL CONDITION: GOOD R #: 19817
OUTSIDE WORK: ADJUSTMENT OF TRIGGER DATE: 9-22-70
ASSEMBLY HAS BEEN CHANGED. FROM: WESTFIELD,
FIRED AMMO TYPE: - MASS.
& CONDITION: _____ GUN #: 123051
PROOF: R.E.P. INSP.: _____ TEST: _____ CODE: WR = 8/68
HEADING: _____ GA. CAL.: 308 WIN.
BREECH OPENING: _____ CHECKED BY: C. PROSSER
RECOIL SHOULDERS: _____ APPROVED: _____
CHAMBER: _____ APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER CONNECTOR BROKEN

COMPLAINT: FOLLOWS DOWN.

INCIDENT: THE BROKEN TRIGGER CONNECTOR WOULD NOT
FUNCTION PROPERLY.

COMMENTS: ALL THREE TRIGGER ADJUSTING SCREWS
HAD BEEN RE-ADJUSTED, PROBABLY IN AN ATTEMPT
TO CORRECT THE FOLLOW DOWN CONDITION CAUSED
BY THE BROKEN PART.