

CLASSIFIED-CONFIDENTIAL

CC: S. E. Davis; In
W. D. Brown/Turn
V. G. Lelean
E. H. Grace
D. C. Foote
H. J. Buchanan
W. C. Coes
P. D. Wetherford
W. H. Fisher

September 12th, 1947

TO:

G. E. Pincney
Bridgeport

FROM:

E. E. Leek

SUBJECT:

W/70 WINCHESTER AT EXTREME LOW TEMPERATURE CONDITIONS

In answer to your letter of August 29th, 1947, previous testing has shown the following:

1. The ice will not adhere to the parts in question if they are well lubricated with Gynolite or Pennington Oil. However it is not likely that the shooter would lubricate his gun in that section as it is not a functioning part of the gun.
2. The Trigger Guide Plate is used as a spacer only between the Trigger Guard and the Stock. If it is made of a plastic material, it is used in this use would not introduce difficulties under normal or adverse conditions, and the nature of the material prevents a bonding of ice to its surface.
3. I would not guarantee that the gun would not freeze under 32°F.
4. A W/70 Winchester under similar conditions (-60°F.) will fire the first round. The bolt will not unlock because ice jams between the bolt spring lug on the bolt and the recess for this spring lug in the receiver.
5. When comparing the trigger and the space between the Trigger and Guide Plate in the W/70 and W/71 respectively, it will be noticed that there is approximately 1/8" more clearance between the Trigger and the Trigger slot in the Guard of the W/70 than there is in the W/71. It may also be noted that the Trigger Pin in the W/70 is located much higher than the W/71, allowing the Trigger to shear the ice in that section around the trigger slot in the Guard, while in the W/71 the Trigger and Trigger Guide Plate causes the ice to be in compression. In the former case the ice breaks and allows the shooter to fire, while in the latter case (W/71) the ice is in compression and prevents firing.
6. I would like to stress the point that this ice is not a hard mass in the section as a rigid block, but the section is sectioned.

If there is any further information needed, please let me know.

E. E. Leek
Engineering Section
Technical Assistant

PLAINTIFF'S
EXHIBIT

3080

AL 0023221

104/