

REMINGTON ARMS COMPANY, INC. - ILION WORKS
Investigator's Copy of Suggestion

NAME: GEORGE PROSSER 82 20692
6282 2023 82 84447

SUGGESTION NO: 73-1-306

CLOCK NO: _____

DATE RECEIVED: 1-19-73

M/580-1-2; 591-2; 788 Trigger Housing Assembly. Change design of Safety and Sear. Alter the M/540X Sear to provide a notch to control engagement between the Sear and Trigger which will not affect its use on the M/540X. Alter the M/580 & 788 Safety to function like the M/540X with the Sear instead of actuating a Safety Plunger. Make minor change to M/580 & 788 Housing to provide clearance for the M/540X type Sear and substitution of the M/540X Safety Plunger & Spring for the M/580 & 788 Safety Plunger and Spring. (NOTE: RD has marked prints). Eliminate Trigger Housing Sub Assy Op. #10-12-153. Eliminate scrap that is now produced at Op. #10. Improve quality by reducing play between Sear and Trigger.

SUPERVISION -

This Suggestor is a member of your area. PLEASE GIVE THIS YOUR PROMPT ATTENTION AND COMMENTS.

If the Suggestion should not be adopted, please write your detailed reasons, as the Suggestor deserves every consideration possible.

If it is adaptable, you are expected to expedite its installation or contact the respective Section (Engineering, Production, Safety, PEAC, etc.) for approval or assistance.

When it is in effect, return all answers to the Suggestion Committee Secretary.

S. P. Alvis - 2/6/73

you comments please!

Suggest mark and auto being indicated to check function and safety aspects. Research has been completed and a minor change and change in both models. I design approved to be held for economic evaluation.

R. H. Brown 2/6/73

RD-6562

R. H. Brown / MLE
 Secretary, Suggestion Committee